

2 Williams Street
Chelsea, MA 02150
(617) 889 - 6515



QUALITY CERTIFICATE

Vessel	Submitted	Port	Providence, RI	Report	044705
Customer	Sprague Energy	Date	May 1, 2005	Reference	
Operation	Analysis	Terminal	Sprague Providence	Sample #	881961

Name of material being tested
Description of sample source
Samples Drawn by (company)
Samples Tested by (company)

No 6 Fuel Oil

Shore Tank#6 After Discharge
BSi Inspectorate
BSi Inspectorate

Tests being Performed	Test method	Sample Results		
Gravity API @ 60F / Denisty	D - 4052	11.3	/	0.9906
Flash Point, PMCC, F	D - 93		180	
Viscosity cSt @ 122F	D - 445		326.4	
Viscosity SSF @ 122F	D - 2161		154.1	
Pour Point C / F	D - 97		0 / 32	
Sulfur , Wt%	D - 4294		0.921	
Water and Sediment, Vol %	D - 1796		0.05	
Sediment by Extraction, wt%	D - 473		0.081	
Water by Distillation, Vol%	D - 95		0.2	
Gross Heat of Combustion, BTU / lb	D - 240		18,283	
Gross Heat of Combustion, BTU / gal	D - 240		150,879	
Ash, wt %	D - 482		0.042	
Vanadium, ppm	D - 5863		17	
Sodium, ppm	D - 5863		11	
Nitrogen, wt%	D - 5762		0.4032	
Ashphaltenes, wt%	IP - 143		0.26	
Carbon Res., Ramsbottom on 10% bottom	D - 189		8.72	
<p>SPRAGUE PROVIDES THE ATTACHED INSPECTION REPORT/ANALYSIS REPRESENTING THE SPECIFICATIONS OF THE PRODUCT AT THE SPRAGUE TERMINAL IN TANK ON THE DATE OF INSPECTION NOTED ON THE CERTIFICATE. THIS ANALYSIS IS PROVIDED TO THE CUSTOMER FOR THE PURPOSE OF ESTABLISHING THE INDEPENDENTLY VERIFIED PRODUCT SPECIFICATION ON A COMPOSITE BASIS IN SPRAGUE'S TERMINAL SHORE TANK AS NOTED ON THE CERTIFICATE. THE INSPECTION REPORT IS NOT TO BE USED FOR ANY OTHER PURPOSE. SPRAGUE DISCLAIMS ANY LIABILITY FOR THE PRODUCT AFTER DELIVERY BY SPRAGUE TO CUSTOMER. SPRAGUE DISCLAIMS ANY WARRANTY OF MERCHANTABILITY OR FITNESS FOR AN INTENDED USE EXCEPT AS MAY BE SPECIFICALLY SET FORTH IN WRITING IN ANY CONTRACT OR TERMS OF SALE BETWEEN SPRAGUE AND A BUYER OF PRODUCT. SPRAGUE ASSUMES NO LIABILITY FOR CLAIMS OR LOSSES THAT MAY ARISE FROM CUSTOMER'S USE OF THIS INSPECTION REPORT/ANALYSIS.</p>				

** Annotates Analysis Contracted Out

*** Annotates Loadport information- this test was not performed by Inspectorate